

# Motorola Gm3688 Service Manual

## GENERAL INFORMATION

The RKN4074 Programming Test Cable connects the radio to the RLN4008 Radio Interface Box (RIB) for radio programming, and/or to the RLN4460 Radio Test Set for radio testing. The RIB and the radio test set can be connected at the same time and not interfere with each other.


## SERVICE

The RKN4074 Programming Test Cable is not repairable. Order a replacement cable as necessary.


## CONNECTOR DETAIL

P2  
TO RADIO  
TEST SET

J1  
TO RIB  
RLN4008



## SCHEMATIC DIAGRAM



DOWNLOAD: <https://tinurli.com/29kz0d>



Download from  
Dreamstime.com  
This watermark-free content is for personal use only.

2468711  
Milan Sturkalis | Dreamstime.com

---

a9c2e16639

[The Sky Is Everywhere Jandy Nelson Free Pdf Downlo](#) [dinsaure britannic](#)  
[chennai local bus routes and numbers pdf download](#)  
[NordVPN 5.4.2 Crack FREE Download](#)  
[Saare Jahaan Se Mehnga 1080p hindi movies](#)  
[bal ganesh 3 full movie in hindi download](#)  
[Ninja-Painter-2-Game](#)  
[namaskar maza ya dnyanmandira download](#)  
[Filemaker Pro 9 Mac Download](#)  
[Glee Season 2 Complete 720p WEBDL](#)  
[Home Security Camera Alfred Mod](#)